

SL-157 Piper PA-14/PA-16/PA-20 Loose Connections

Last Modified on 04/11/2022 4:20 pm MDT

Piper Service Letter No. 157

Applicability: Piper PA-14, PA-16 and PA-20

System: Electrical

Issue Date: August 1, 1950

Subject: Loose Connections

Summary: Trouble with the starter button sticking as a result of a loose connection in the starting circuit.

Open PDF: [PIP_SL157.pdf](#) 
