

SB-183 Piper Tail Brace Streamline Tie Rods

Last Modified on 04/12/2022 1:28 pm MDT

Piper Service Bulletin No. 183

Applicability: Piper PA-12, PA-14, PA-20, PA-22, PA-22 "135", PA-22 "150", PA-22 "160"

System: Tail Section

Issue Date: November 9, 1959

Subject: Tail Brace Streamline Tie Rods

Summary: Reported cases of failure of a tail brace wire (10074-02 or 10074-03) on the above listed airplanes.

Open PDF: [PIP_SB183.pdf](#) 
