

SB-218 Piper Replacement of Vacuum Pump Splined Coupling

Last Modified on 04/12/2022 1:32 pm MDT

Piper Service Bulletin No. 218

Applicability:

- Piper PA-18
- Piper PA-22-108
- Piper PA-23-235 and PA-23-250
- Piper PA-24 and PA-24 "250"
- Piper PA-30

System: Engine

Issue Date: November 11, 1963

Subject: Replacement of Vacuum Pump Splined Coupling

Summary: Reports of the vacuum pump splined coupling on Airborne Mechanisms Vacuum Pumps Models 113A5 and 113A8 may fail prematurely as a result of over-curing.

Open PDF: [PIP_SB218.pdf](#) 
