

# SB-573 Piper Wing Fuel Tank Cap Modification

Last Modified on 04/12/2022 1:47 pm MDT

## Piper Service Bulletin No. 573

**Applicability:** Piper PA-11, PA-12, PA-14, PA-16, PA-18 serial numbers 18-1 thru 18-7609068, PA-20, PA-22

**System:** Fuel

**Issue Date:** February 8, 1978

**Subject:** Wing Fuel Tank Cap Modification

**Summary:** A recent fuel tank collapse was attributed to inadequate venting, caused by obstruction of the cap vent holes installed per Piper Service Bulletin No. 522.

**Open PDF:** [PIP\\_SB573.pdf](#) 

---