

# SB-819 Piper Fuselage Door Frame Tube Corrosion

Last Modified on 04/12/2022 1:54 pm MDT

## Piper Service Bulletin No. 819

### Applicability:

- Piper J-4 Coupe serial numbers 4-401 thru 4-1649
- Piper J-5 Cruiser serial numbers 5-02 thru 5-1389
- Piper PA-12 Super Cruiser serial numbers 12-02 thru 12-4036
- Piper PA-14 Family Cruiser serial numbers 14-01 thru 14-523
- Piper PA-15 Vagabond serial numbers 15-01 thru 15-388
- Piper PA-16 Clipper serial numbers 16-01 thru 16-736
- Piper PA-17 Vagabond serial numbers 17-01 thru 17-215
- Piper PA-20 Pacer serial numbers 20-01 thru 20-1121
- Piper PA-22 Tripacer and Colt serial numbers 22-01 thru 22-9848

**System:** Airframe

**Issue Date:** February 28, 1986

**Subject:** Fuselage Door Frame Tube Corrosion

**Summary:** Compromised structural integrity of the fuselage due to excessive rust and corrosion between steel tubing and preformed sheet steel material.

**Open PDF:** [PIP\\_SB819.pdf](#) 

---