

SL-349 Piper Adjustment of Engine Support Bushings

Last Modified on 04/12/2022 3:55 pm MDT

Piper Service Letter No. 349

Applicability: Piper PA-18, PA-22 and PA-25 series aircraft equipped with Lycoming engines

System: Engine

Issue Date: December 14, 1960

Subject: Adjustment of Engine Support Bushings

Summary: Per Lycoming Division of Avco Corporation, it is permissible to use a torque value of 40 inch pounds to provide adequate tightness to maintain proper engine support in lieu of the linear dimension as previously specified.

Open PDF: [PIP_SL349.pdf](#) 
