

# VSP-100 Piper Defective Diagrams in Master Cylinder

Last Modified on 04/13/2022 9:35 am MDT

## Piper Vendor Service Publication No. 100

**Referenced Vendor:** Scott Service Bulletin No. 1248H-32-53

### **Applicability:**

- Piper J-3 Cub
- Piper PA-11 Cub Special
- Piper PA-12 Super Cruiser
- Piper PA-18 Super Cub
- Piper PA-19 Super Cub
- Piper PA-22 Tripacer/Colt

**System:** Brake

**Issue Date:** November 10, 1989

**Subject:** Defective Diagrams in Master Cylinder

**Summary:** Information on replacing an existing diaphragm suspected to be defective in master brake cylinders installed in listed Piper aircraft models.

**Open PDF:** [PIP\\_VSP-100.pdf](#) 

---