

VSP-100 Piper Defective Diagrams in Master Cylinder

Last Modified on 04/13/2022 9:35 am MDT

Piper Vendor Service Publication No. 100

Referenced Vendor: Scott Service Bulletin No. 1248H-32-53

Applicability:

- Piper J-3 Cub
- Piper PA-11 Cub Special
- Piper PA-12 Super Cruiser
- Piper PA-18 Super Cub
- Piper PA-19 Super Cub
- Piper PA-22 Tripacer/Colt

System: Brake

Issue Date: November 10, 1989

Subject: Defective Diagrams in Master Cylinder

Summary: Information on replacing an existing diaphragm suspected to be defective in master brake cylinders installed in listed Piper aircraft models.

Open PDF: [PIP_VSP-100.pdf](#) 
