

# SL-100 Univair Stamped Piper Aluminum Rib Field Repair Process

Last Modified on 04/13/2022 9:49 am MDT

## Univair Service Letter No. 100

**Applicability:** Piper J-3, J-5C, PA-11, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, PA-20, PA-22, PA-25

**System:** Wing

**Issue Date:** October 28, 2004

**Subject:** Stamped Piper Aluminum Rib Field Repair Process

**Summary:** Outlines the repair of Univair STC'd Stamped Ribs in accordance with the original STC and FAA Advisory Circular AC 43.13-1B.

**Open PDF:** [UAC\\_SL-100.pdf](#) 

---