

SL-100 Univair Stamped Piper Aluminum Rib Field Repair Process

Last Modified on 04/13/2022 9:53 am MDT

Univair Service Letter No. 100

Applicability: Piper J-3, J-5C, PA-11, PA-12, PA-14, PA-15, PA-16, PA-17, PA-18, PA-20, PA-22, PA-25

System: Wing

Issue Date: October 28, 2004

Subject: Stamped Piper Aluminum Rib Field Repair Process

Summary: Outlines the repair of Univair STC'd Stamped Ribs in accordance with the original STC and FAA Advisory Circular AC 43.13-1B.

Open PDF: [UAC_SL-100.pdf](#) 
