

# SB-174B Piper Inspection and Maintenance of Fuselage Fabric Around Windshield Top

Last Modified on 04/12/2022 1:19 pm MDT

## Piper Service Bulletin No. 174B

### Applicability:

- All Piper J-4, J-5, PA-12, PA-14, PA-15, PA-16, PA-17 and PA-20 airplanes
- Piper PA-22 serial numbers 22-1 thru 22-7999

**System:** Airframe

**Issue Date:** November 30, 1961

**Subject:** Inspection and Maintenance of Fuselage Fabric in Area of Windshield Top Attachment Channel

**Summary:** How to fix difficulties with the fabric where it attaches to the fuselage under the windshield top and/or directly over the rear edge of the windshield top attachment channel.

**Open PDF:** [PIP\\_SB174B.pdf](#) 

---