

SB-174B Piper Inspection and Maintenance of Fuselage Fabric Around Windshield Top

Last Modified on 04/12/2022 1:20 pm MDT

Piper Service Bulletin No. 174B

Applicability:

- All Piper J-4, J-5, PA-12, PA-14, PA-15, PA-16, PA-17 and PA-20 airplanes
- Piper PA-22 serial numbers 22-1 thru 22-7999

System: Airframe

Issue Date: November 30, 1961

Subject: Inspection and Maintenance of Fuselage Fabric in Area of Windshield Top Attachment Channel

Summary: How to fix difficulties with the fabric where it attaches to the fuselage under the windshield top and/or directly over the rear edge of the windshield top attachment channel.

Open PDF: [PIP_SB174B.pdf](#) 
