

# SB P-1 Univair Throttle Inspection in Piper Airplanes

Last Modified on 04/12/2022 2:11 pm MDT

## Univair Service Bulletin No. P-1

**Applicability:** Piper J-3, PA-11, PA-12 and PA-18

**System:** Control

**Issue Date:** August 10, 2007

**Subject:** Throttle Inspection in Piper J-3, PA-11, PA-12 and PA-18 Airplanes

**Summary:** Steps to preclude failure of the U12694 series throttle cables, which could cause loss of full travel of the throttle control.

**Open PDF:** [UAC\\_sb-p1.pdf](#) 

---