

SB P-1 Univair Throttle Inspection in Piper Airplanes

Last Modified on 04/12/2022 2:12 pm MDT

Univair Service Bulletin No. P-1

Applicability: Piper J-3, PA-11, PA-12 and PA-18

System: Control

Issue Date: August 10, 2007

Subject: Throttle Inspection in Piper J-3, PA-11, PA-12 and PA-18 Airplanes

Summary: Steps to preclude failure of the U12694 series throttle cables, which could cause loss of full travel of the throttle control.

Open PDF: [UAC_sb-p1.pdf](#) 
