

SL-169 Piper Manifold Pressure Gauge Installation

Last Modified on 04/12/2022 3:05 pm MDT

Piper Service Letter No. 169

Applicability: All 1951 Piper Models

System: Instrumentation

Issue Date: April 20, 1951

Subject: Manifold Pressure Gauge Installation

Summary: Remedy for manifold pressure gauges installed in 1951 model airplanes giving unsatisfactory service.

Open PDF: [PIP_SL169.pdf](#) 
