

SL-213 Piper Primer Lines

Last Modified on 04/12/2022 3:10 pm MDT

Piper Service Letter No. 213

Applicability: Piper PA-18, PA-20 and PA-22

System: Fuel

Issue Date: October 7, 1953

Subject: Primer Lines

Summary: To prevent excessive wear of the primer line, resulting in fuel leakage and possible cabin fire, it is recommended that primer lines be clamped and/or re-routed per the sketch included with this letter.

Open PDF: [PIP_SL213.pdf](#) 
