

SL-223 Piper Engine Support Bushings

Last Modified on 04/12/2022 3:19 pm MDT

Piper Service Letter No. 223

Applicability: Piper PA-12, PA-16, PA-18, PA-18A, PA-20 and PA-22

System: Engine

Issue Date: May 17, 1954

Subject: Engine Support Bushings

Summary: Discussion concerning the useful life of the eight rubber engine support bushings, Lycoming part number 60883.

Open PDF: [PIP_SL223.pdf](#) 
