

# SL-259 Piper RPM Restriction Placard

Last Modified on 04/12/2022 3:32 pm MDT

## Piper Service Letter No. 259

### Applicability:

- Piper PA-18 "150"
- Piper PA-18A "150"
- Piper PA-22 "150"

**System:** Operations

**Issue Date:** November 30, 1955

**Subject:** RPM Restriction Placard

**Summary:** The RPM restriction placard is no longer necessary and can be removed from above mentioned airplanes.

**Open PDF:** [PIP\\_SL259.pdf](#) 

---