

# SL-362B Piper Modification of Windshield Top Attachment

Last Modified on 04/12/2022 4:04 pm MDT

## Piper Service Letter No. 362B

### Applicability:

- PA-12 Super Cruiser serial numbers 12-2904 thru 12-2906, 12-2908 thru 12-2910, 12-2913, 12-2916, 12-2918 thru 12-2924, 12-2926 thru 12-2949, 12-2951 thru 12-3027, 12-3029 to 12-3900, and 12-3904 thru 12-4036
- PA-14 Family Cruiser serial numbers 14-1 thru 14-11
- PA-15 Vagabond serial numbers 15-1 thru 15-388
- PA-16 Clipper serial numbers 16-1 thru 16-137
- PA-17 Vagabond Trainer serial numbers 17-1 thru 17-215
- PA-20 Pacer serial numbers 20-1 thru 20-1121
- PA-22 Tri-Pacer serial numbers 22-1 thru 22-7630

**System:** Airframe

**Issue Date:** December 11, 1974

**Subject:** Modification of Windshield Top Attachment

**Summary:** Material list and instructions to reinforce the area where the fabric attaches to the fuselage under the windshield top and/or directly over the rear edge of the windshield top attachment channel.

**Open PDF:** [PIP\\_SL362B.pdf](#) 

---