

# SL-400 Piper Replacement of Tailbrace Rods

Last Modified on 04/12/2022 4:16 pm MDT

## Piper Service Letter No. 400

### Applicability:

- All Piper PA-12 aircraft
- All Piper PA-14 aircraft
- All Piper PA-20 aircraft
- PA-22 Tri-Pacer serial numbers 22-1 thru 22-7999

**System:** Tail Section

**Issue Date:** May 31, 1974

**Subject:** Replacement of Tail Brace Rods

**Summary:** The round upper and lower tail brace tie rod assemblies, part numbers 10555-02 and 10556-02, respectively, have been approved to replace the upper and lower streamline tail brace tie rod assemblies in the listed aircraft.

**Open PDF:** [PIP\\_SL400.pdf](#) 

---