

SB-120 Piper J-3/PA-11 Replacement of Front and Rear Lift Strut Forks and Barrels

Last Modified on 04/11/2022 3:28 pm MDT

Piper Service Bulletin No. 120

Applicability: Piper J-3 and PA-11

System: Wing

Issue Date: March 28, 1952

Subject: Replacement of Front and Rear Lift Strut Forks and Barrels

Summary: Failures of lift struts caused by abuse, failure to replace lift struts after ground accidents, and the use of damaged parts from scrapped airplanes as service replacement parts.

Open PDF: [PIP_SB120.pdf](#) 
