

SA MISC/TP-1001A Piper Engine Mounting

Last Modified on 04/12/2022 2:15 pm MDT

Piper Service Aid MISC/TP-1001A

Applicability: Piper PA-18, PA-22, PA-22-108 and PA-25

System: Engine

Issue Date: -

Subject: Engine Mounting

Summary: Tightening engine mounting bolts to obtain a torque of (40) inch pounds.

Open PDF: [PIP_MISC-TP-1001A.pdf](#) 
