

SL-233 Piper Fuel Selector Valve

Last Modified on 04/12/2022 3:30 pm MDT

Piper Service Letter No. 233

Applicability:

- PA-18 "105", "125" and "135" equipped with two wing fuel tanks
- PA-20 "115", "125" and "135" equipped with two wing fuel tanks
- PA-22 "125" and "135" equipped with two wing fuel tanks

System: Fuel

Issue Date: October 22, 1959

Subject: Fuel Selector Valve

Summary: The new Fuel Selector Valve, part number 11383-04, should be used for all service replacements and all new installations on Piper PA-18, PA-20 and PA-22 airplanes equipped with two wing fuel tanks.

Open PDF: [PIP_SL233.pdf](#) 
